

L Number	Hits	Search Text	DB	Time stamp
9	51	oil same (repellant adj3 finish\$4)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/05/30 14:30
10	10	(oil same (repellant adj3 finish\$4)) and motor	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/05/30 14:30
-	1	("6339237").PN.	USPAT	2002/05/29 10:28
-	5	("5331191" "6077763" "6090660" "6127702" "6143594").PN.	USPAT	2002/05/29 10:26
-	21	310/67r.ccls. and @pd>20011211	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/05/29 15:10
-	24	310/90.ccls. and @pd>20011211	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/05/29 15:12
-	8	("3961864" "4128364" "4130770" "4682065" "4686400" "5013957" "5170086" "5245236").PN.	USPAT	2002/05/29 15:28
-	7	("4980587" "5381066" "5729404" "5768051" "5844748" "5880543" "6005746").PN.	USPAT	2002/05/29 15:29
-	5	("5433529" "5504637" "5516212" "5559382" "5658080").PN.	USPAT	2002/05/29 15:31
-	6	("5214326" "5281886" "5347189" "5402023" "5448119" "5483113").PN.	USPAT	2002/05/29 15:41
-	7	("3778123" "4445793" "4892418" "5112142" "5246294" "5427456" "5433529").PN.	USPAT	2002/05/29 15:42
-	373322	bearing and shaft	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/05/29 15:52
-	126588	(bearing and shaft) and (oil\$3 or lubrica\$4 or fluid\$3)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/05/29 15:53
-	45589	((bearing and shaft) and (oil\$3 or lubrica\$4 or fluid\$3)) and groove\$3	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/05/29 15:53
-	15285	((bearing and shaft) and (oil\$3 or lubrica\$4 or fluid\$3)) and groove\$3) and disk	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/05/29 15:54
-	336	((bearing and shaft) and (oil\$3 or lubrica\$4 or fluid\$3)) and groove\$3) and disk) and @pd>20011211	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/05/29 15:55
-	21	((bearing and shaft) and (oil\$3 or lubrica\$4 or fluid\$3)) and groove\$3) and disk) and @pd>20011211) and 310/\$.ccls.	USPAT; EPO; JPO; DERWENT; IBM_TDB	2002/05/29 15:56

sin·ter

sin·ter (sĭn'tĕr) *noun*

1. *Geology.* A chemical sediment or crust, as of porous silica, deposited by a mineral spring.
2. A mass formed by sintering.

verb

sin·tered, sin·ter·ing, sin·ters *verb, transitive*

To cause (metallic powder, for example) to form a coherent mass by heating without melting.

verb, intransitive

To form a coherent mass by heating without melting.

[German, from Middle High German, dross, metal slag, from Old High German.]

— **sin ter·a·bil i·ty** *noun*

The American Heritage® Dictionary of the English Language, Third Edition copyright © 1992 by Houghton Mifflin Company. Electronic version licensed from INSO Corporation; further reproduction and distribution restricted in accordance with the Copyright Law of the United States. All rights reserved.